Notes for setup:
Step 1 - Set the frog polarity - if it is the wrong way round reverse, the connection on the point motor, DCC In.
Step 2 - Set the correct LM-iD to move the point the correct way, reverse the connections in PBS-L & PBS-R.
Step 3 - Set the loop polarity, swap connections X1 and X2 if required - see middle right on diagram.

General Note:
The reversing loop must be longer
than the longest train to use it.

Make sure this distance leaves
enough time for the point to
change before the train
reaches the point

= Track break

LM-iD.1

X1   X2

DCCconcepts
Cobalt REX

Versatile SPDT Relay Interface

DCP-CB1DIP

DCP-REX